

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	OE Supplier	Schrader Sensor #	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	OE Sensor Part #
Acura	CSX	08-09	35	TRW	28720			1212	2040K	42753-SNA-A83
Acura	MDX	04-06	35	TRW	28981			1057	2000K	06421-S3V-A04
Acura	MDX	07-11	35	Pacific	20098			1209	1100K	42753-STK-A04
Acura	RDX	07-11	35	Pacific	20098			1209	1100K	42753-STK-A04
Acura	RL	05-08	35	TRW	28981			1057	2000K	06421-S3V-A04
Acura	RL	09-11	35	TRW	28981			1057	2040K or 2000K	42753-SHJ-A53
Acura	TL	05-08	35	TRW	28981			1057	2000K	06421-S3V-A04
Acura	TL(Hi-Line)	09-11	35	TRW	20720			1214	2040K	42753-TK4-A01
Acura	TSX	07-11	35	Pacific	20098			1209	1100K	42753-TL2-A52
Acura	ZDX(Hi-Line)	10-11	35	TRW	20720			1214	2040K	42753-TK4-A01
Audi	Allroad(315 Mhz)	01-05	35	Beru				9004	1090K	4D0 907 275A
Audi	A6 Allroad(433 Mhz)	01-06	35	Beru	20077			9001	1090K	4D0 907 275C
Audi	A6 Allroad(433 Mhz)	07-09	35	Beru	20078			9007	1090K	4F0 907 275B
Audi	A6 Allroad(433 Mhz)-- Post June 2009	10	35	Beru	20103			9011	1090K	4F0 907 275D
Audi	A3(315 Mhz)	06-11	71	Siemens	20088			1053	1030K	1K0907253D
Audi	A4(433 Mhz)	02-08	35	Beru	20078			9007	1090K	4F0 907 275B
Audi	A4 (315 Mhz)	09-11	71	Continental	20088			1053	1030K	1K0907253D
Audi	A5(315 Mhz)	08-11	71	Siemens	20088			1053	1030K	1K0907253D
Audi	A6(315 Mhz)	02-04	35	Beru				9004	1090K	4D0 907 275A
Audi	A6(433 Mhz)	05-09	35	Beru	20078			9007	1090K	4F0 907 275B
Audi	A6(433 Mhz)-- Post June 2009	10-11	35	Beru	20103			9011	1090K	4F0 907 275D
Audi	A8(315 Mhz)	01-07	35	Beru				9004	1090K	4D0 907 275A
Audi	A8(433 Mhz)	00-11	35	Beru	20077			9001	1090K	4D0 907 275C
Audi	Q5(315 Mhz)	09-11	71	Continental	20088			1053	1030K	1K0907253D
Audi	Q7(433 Mhz)	05-09	35	Beru	20078			9007	1090K	4F0 907 275B
Audi	Q7(433 Mhz)-- Post June 2009	10-11	35	Beru	20103			9011	1090K	4F0 907 275D
Audi	R8(433 Mhz)	08-09	35	Beru	20078			9007	1090K	4F0 907 275B
Audi	R8(433 Mhz)-- Post June 2009	10-11	35	Beru	20103			9011	1090K	4F0 907 275D
Audi	RS4(433 Mhz)	07-09	35	Beru	20078			9007	1090K	4F0 907 275B
Audi	RS6(315 Mhz)	01-05	35	Beru				9004	1090K	4D0 907 275A
Audi	RS6(433 Mhz)	01-05	35	Beru	20077			9001	1090K	4D0 907 275C
Audi	S4(433 Mhz)	02-08	35	Beru	20078			9007	1090K	4F0 907 275B
Audi	S4(315 Mhz)	10-11	71	Siemens	20088			1053	1030K	1K0907253D
Audi	S5(315 Mhz)	08-11	71	Siemens	20088			1053	1030K	1K0907253D
Audi	S6(433 Mhz)	04-09	35	Beru	20078			9007	1090K	4F0 907 275B
Audi	S6(433 Mhz)-- Post June 2009	10-11	35	Beru	20103			9011	1090K	4F0 907 275D
Audi	S8(315 Mhz)	01-07	35	Beru				9004	1090K	4D0 907 275A
Audi	S8(433 Mhz)	00-09	35	Beru	20077			9001	1090K	4D0 907 275C
Audi	TT(315 Mhz)	08-11	71	Siemens	20088			1053	1030K	1K0907253D
Bentley	Continental GT--433 Mhz	03-05	35	Beru	20077			9001	1090K	4D0 907 275C
Bentley	Continental GT--433 Mhz (Post May)	05-11	35	Beru	20078			9007	1090K	4F0 907 275B
Bentley	Azure--433 Mhz	07-09	35		20078			9007	1090K	4F0 907 275B
Bentley	Mulsanne--433 Mhz	11-12	35		20078			9007	1090K	4F0 907 275B
Bentley	Flying Spur--433 Mhz	05-10	35		20078			9007	1090K	4F0 907 275B
BMW	1 Series(433 Mhz)	07-11	35	Beru	20083			1027	1090K	36 23 6 781 847
BMW	1 Series(433 Mhz)-- September, 2010	11	35	Beru	28081			9012	2000K	36 10 6 790 054
BMW	3 Series(315 Mhz)	00-02	35	Beru				9004	1090K	36 11 8 378 681
BMW	3 Series(433 Mhz)	01-06	35	Beru	20080			9002	1090K	36 11 8 378 682
BMW	3 Series(433 Mhz)	07-10	35	Beru	20083			1027	1090K	36 23 6 781 847
BMW	3 Series(433 Mhz)-- September 2009	10-11	35	Beru	28081			9012	2000K	36 10 6 790 054

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	OE Supplier	Schrader Sensor #	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	OE Sensor Part #
BMW	5 Series(315 Mhz)	00-02	35	Beru				9004	1090K	36 11 8 378 681
BMW	5 Series(433 Mhz)	02-05	35	Beru	20080			9002	1090K	36 11 8 378 682
BMW	5 Series(433 Mhz)	06-11	35	Beru	20083			1027	1090K	36 23 6 781 847
BMW	5 Series(433 Mhz)-- September, 2010	11	35	Beru	28081			9012	2000K	36 10 6 790 054
BMW	6 Series(433 Mhz)	06-10	35	Beru	20083			1027	1090K	36 23 6 781 847
BMW	7 Series(315 Mhz)	00-01	35	Beru				9004	1090K	36 11 8 378 681
BMW	7 Series(433 Mhz)	02-05	35	Beru	20080			9002	1090K	36 11 8 378 682
BMW	7 Series(433 Mhz)	06-11	35	Beru	20083			1027	1090K	36 23 6 781 847
BMW	7 Series(433 Mhz)-- September, 2010	11	35	Beru	28081			9012	2000K	36 10 6 790 054
BMW	M Series(433 Mhz)	06-10	35	Beru	20083			1027	1090K	36 23 6 781 847
BMW	M Series(433 Mhz)-- September 2009	10-11	35	Beru	28081			9012	2000K	36 10 6 790 054
BMW	X3(433 Mhz)	06-10	35	Beru	20083			1027	1090K	36 23 6 781 847
BMW	X3(433 Mhz)	11	35	Beru	28081			9012	2000K	36 10 6 790 054
BMW	X5(433 Mhz)	01-04	35	Beru	28082			9003	1090K	36 14 6 752 128
BMW	X5(433 Mhz)	05-11	35	Beru	20083			1027	1090K	36 23 6 781 847
BMW	X5(433 Mhz)-- October, 2010	11	35	Beru	28081			9012	2000K	36 10 6 790 054
BMW	X6(433 Mhz)	08-11	35	Beru	20083			1027	1090K	36 23 6 781 847
BMW	X6(433 Mhz)-- October, 2010	11	35	Beru	28081			9012	2000K	36 10 6 790 054
BMW	Z Series(433 Mhz)	06-10	35	Beru	20083			1027	1090K	36 23 6 781 847
BMW	Z Series(433 Mhz)-- September 2009	10-11	35	Beru	28081			9012	2000K	36 10 6 790 054
BMW	Alpina(433 Mhz)	04-08	35	Beru	20080			9002	1090K	36 11 8 378 682
Bugatti	Veyron	05-06	NA	Beru				NA	1090K	NA
Buick	Allure	07-08	80	Siemens	20158	7001	7000K	1047	1050K	15921013
Buick	Allure	09-10	---	Schrader	20153	7001	7000K	9153	VS950	12768826
Buick	Enclave	08	80	Siemens	20158	7001	7000K	1047	1050K	15921013
Buick	Enclave	09-11	---	Schrader	20153	7001	7000K	9153	VS950	25920615
Buick	LaCrosse	07-08	80	Siemens	20158	7001	7000K	1047	1050K	15921013
Buick	LaCrosse	09-11	---	Schrader	20153	7001	7000K	9153	VS950	12768826
Buick	Lesabre	07	---	Schrader	20153	7001	7000K	9153	VS950	25799331
Buick	Lucerne	07-11	---	Schrader	20153	7001	7000K	9153	VS950	25920615
Buick	Ranier	06-07	62	Schrader	20116	7001	7000K	9116	1070K	25774006
Buick	Ranier	07	---	Schrader	20153	7001	7000K	9153	VS950	25799331
Buick	Regal	11	---	Schrader	20153	7001	7000K	9153	VS950	20922900
Cadillac	CTS	04-07	62	Schrader	20116	7001	7000K	9116	1070K	25774006
Cadillac	CTS	08-11	---	Schrader	20153	7001	7000K	9153	VS950	25920615
Cadillac	CTS-V	09-11	---	Schrader	20158	7001	7000K	1047	1050K	15268606
Cadillac	Deville	01-05	62	Schrader	20117			9117	1080K	25773946
Cadillac	DTS	06	80	Schrader	20158	7001	7000K	1047 **	1050K or 1070K	15268606
Cadillac	DTS	07-11	---	Schrader	20153	7001	7000K	9153	VS950	25920615
Cadillac	Escalade-ESV-EXT	04	62	Schrader	20115			9115	1070K	15136883
Cadillac	Escalade-ESV-EXT	05-06	62	Schrader	20107			9107	1070K	15114379
Cadillac	Escalade-ESV-EXT	07	62	TRW		7001	7000K	NA	2020K	15825475
Cadillac	Escalade-ESV-EXT	07	80	Siemens	20158	7001	7000K	1047	1050K	TRW Sensor Replacement
Cadillac	Escalade-ESV-EXT	07-11	---	Schrader	20153	7001	7000K	9153	VS950	25920615
Cadillac	Seville	01-04	62	Schrader	20117			9117	1080K	25773946
Cadillac	SRX	04-06	62	Schrader	20116	7001	7000K	9116	1070K	25774006
Cadillac	SRX	07-11	---	Schrader	20153/28206	7001	7000K	9153	VS950	12768826
Cadillac	STS	05-09	62	Schrader	20076	7001	7000K	9076	1070K	25758220
Cadillac	STS	09	80	Schrader	20158	7001	7000K	1047 **	1050K or 1070K	15268606
Cadillac	STS	09-11	---	Schrader	20153	7001	7000K	9153	VS950	25920615
Cadillac	XLR	04-09	62	Schrader	20076	7001	7000K	9076	1070K	25758220

****The 1050K is to be used on the Siemens sensors and the 1070K is to be used on the Schrader sensors.**

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	OE Supplier	Schrader Sensor #	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	OE Sensor Part #
Chevrolet	Avalanche	04	62	Schrader	20115			9115	1070K	15136883
Chevrolet	Avalanche	05-06	62	Schrader	20107			9107	1070K	15114379
Chevrolet	Avalanche	07	62	TRW		7001	7000K	NA	2020K	15825475
Chevrolet	Avalanche	07	80	Siemens	20158	7001	7000K	1047	1050K	TRW Sensor Replacement
Chevrolet	Avalanche	07-11	---	Schrader	20153	7001	7000K	9153	VS950	25920615
Chevrolet	Aveo	07-11	---	Schrader	20153	7001	7000K	9153	VS950	25920615
Chevrolet	Camaro	10-11	---	Schrader	20153-28206	7001	7000K	9153	VS950	12768826
Chevrolet	Cobalt	08-10	80	Siemens	20158	7001	7000K	1047	1050K	15268606
Chevrolet	Cobalt	08-10	---	Schrader	20153	7001	7000K	9153	VS950	12768826
Chevrolet	Colorado	07-11	62	Schrader	20131			9131	1110K	15122618
Chevrolet	Corvette	97-00	62	Schrader	28006			8006		10438853
Chevrolet	Corvette-C5-Z6	01-04	62	Schrader	20117			9117	1080K	25773946
Chevrolet	Corvette-C6	05-09	62	Schrader	20076	7001	7000K	9076	1070K	25758220
Chevrolet	Corvette	10-11	80	Schrader	20158	7001	7000K	1047 **	1050K or 1070K	15268606
Chevrolet	Cruze	11	---	Schrader	20153	7001	7000K	9153	VS950	12768826
Chevrolet	Equinox	07-09	80	Siemens	20158	7001	7000K	1047	1050K	15921013
Chevrolet	Equinox	10-11	---	Schrader	20153/28206	7001	7000K	9153	VS950	12768826
Chevrolet	Express Series	08-09	80	Siemens	20158	7001	7000K	1047	1050K	15921013
Chevrolet	Express Series	10-11	---	Schrader	20153	7001	7000K	9153	VS950	25920615
Chevrolet	G Series	08	80	Siemens	20158	7001	7000K	1047	1050K	15921013
Chevrolet	HHR	08-09	80	Schrader	20158	7001	7000K	1047 **	1050K or 1070K	15268606
Chevrolet	HHR	08-11	---	Schrader	20153-28206	7001	7000K	9153	VS950	25920615
Chevrolet	Impala	06-07	80	Schrader	20158	7001	7000K	1047 **	1050K or 1070K	15268606
Chevrolet	Impala	07-11	---	Schrader	20153	7001	7000K	9153	VS950	25920615
Chevrolet	Malibu(< 10/14/07)	08	80	Siemens	20158	7001	7000K	1047	1050K	15921013
Chevrolet	Malibu	08-11	---	Schrader	20153-28206	7001	7000K	9153	VS950	12768826
Chevrolet	Monte Carlo	06-07	80	Schrader	20158	7001	7000K	1047 **	1050K or 1070K	15268606
Chevrolet	Monte Carlo	07	---	Schrader	20153	7001	7000K	9153	VS950	25920615
Chevrolet	Silverado	04	62	Schrader	20115			9115	1070K	15136883
Chevrolet	Silverado	05-06	62	Schrader	20107			9107	1070K	15114379
Chevrolet	Silverado	07	62	TRW		7001	7000K	NA	2020K	15825475
Chevrolet	Silverado	07	80	Siemens	20158	7001	7000K	1047	1050K	TRW Sensor Replacement
Chevrolet	Silverado	07-11	---	Schrader	20153	7001	7000K	9153	VS950	25920615
Chevrolet	SSR	06-07	62	Schrader	20116	7001	7000K	9116	1070K	25774006
Chevrolet	Suburban	04	62	Schrader	20115			9115	1070K	15136883
Chevrolet	Suburban	05-06	62	Schrader	20107			9107	1070K	15114379
Chevrolet	Suburban	07	62	TRW		7001	7000K	NA	2020K	15825475
Chevrolet	Suburban	07	80	Siemens	20158	7001	7000K	1047	1050K	TRW Sensor Replacement
Chevrolet	Suburban	07-11	---	Schrader	20153	7001	7000K	9153	VS950	25920615
Chevrolet	Tahoe	04	62	Schrader	20115			9115	1070K	15136883
Chevrolet	Tahoe	05-06	62	Schrader	20107			9107	1070K	15114379
Chevrolet	Tahoe	07	62	TRW		7001	7000K	NA	2020K	15825475
Chevrolet	Tahoe	07	80	Siemens	20158	7001	7000K	1047	1050K	TRW Sensor Replacement
Chevrolet	Tahoe	07-11	---	Schrader	20153	7001	7000K	9153	VS950	25920615
Chevrolet	Trailblazer	06-09	62	Schrader	20116	7001	7000K	9116	1070K	25774006
Chevrolet	Traverse	09-11	62	Schrader	20153	7001	7000K	9153	VS950	25920615
Chevrolet	Uplander	08-09	80	Schrader	20158	7001	7000K	1047 **	1050K or 1070K	15268606
Chevrolet	Volt	10-11	---	Schrader	20153-28206	7001	7000K	9153	VS950	12768826

****The 1050K is to be used on the Siemens sensors and the 1070K is to be used on the Schrader sensors.**

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	OE Supplier	Schrader Sensor #	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	OE Sensor Part #
Chrysler	200	11	71	Continental	20066	7001	7000K	1051	7000K	68078861AA
Chrysler	300	05-07	71	Siemens	20066	7001	7000K	1051	1050K	68111696AA
Chrysler	300(433 Mhz)	08	71	Continental	28155	7004	7000K	1043	1050K	68001698AB
Chrysler	300(433 Mhz)	09-10	71	Schrader	28214-28291			9214	2030K	56029400AD
Chrysler	300(Alloy)	10-11	---	Schrader	20398			9398	VS950	56029398AB
Chrysler	300M(433 Mhz)	02-04	35	Schrader	20028	7004	7000K	9028	1080K	52088990AC
Chrysler	Aspen	07-09	71	Schrader	20066	7001	7000K	1051 **	1050K or 2030K	56029465AB
Chrysler	Concorde(433 Mhz)	02-04	35	Schrader	20028	7004	7000K	9028	1080K	52088990AC
Chrysler	Crossfire(433 Mhz)	04-05	35	Schrader	20028	7004	7000K	9028	1080K	52088990AC
Chrysler	Crossfire	05	35	Schrader	20066	7001	7000K	1051 **	1050K or 2030K	56053030AB
Chrysler	Crossfire(433 Mhz)	06-08	35	Schrader	20028	7004	7000K	9028	1080K	52088990AC
Chrysler	Crossfire	06-08	71	Siemens	20066	7001	7000K	1051	1050K	56053030AB
Chrysler	Pacifica(433 Mhz)	04	35	Schrader	20028	7004	7000K	9028	1080K	52088990AC
Chrysler	Pacifica	04-05	71	Siemens	20335	7001	7000K	1052	1050K	04727392AB
Chrysler	Pacifica	06-08	71	Siemens	20066	7001	7000K	1051	1050K	68001696AB
Chrysler	Prowler	01	35	Schrader	28004			8004	1080K	4815132AB
Chrysler	Prowler(433 Mhz)	02	35	Schrader	20028	7004	7000K	9028	1080K	52088990AC
Chrysler	PT Cruiser	08-10	71	Siemens	20066	7001	7000K	1051	1050K	68001696AB
Chrysler	Sebring(433 Mhz)	08-09	71	Continental	28155	7004	7000K	1043	1050K	68001698AB
Chrysler	Sebring(315 Mhz)	07-10	71	Siemens	20066	7001	7000K	1051	1050K	68001696AB
Chrysler	Sebring(315 Mhz)	10-11	71	Continental	20066	7001	7000K	1051	7000K	68078861AA
Chrysler	Town & Country(433 Mhz)	02-03	35	Schrader	20028	7004	7000K	9028	1080K	52088990AC
Chrysler	Town & Country	04-05	71	Siemens	20335	7001	7000K	1052	1050K	04727392AB
Chrysler	Town & Country	06-08	71	Siemens	20066	7001	7000K	1051	1050K	56053030AB
Chrysler	Town & Country (433 Mhz)	08-10	71	Continental	28155	7004	7000K	1043	1050K	68001698AB
Chrysler	Town & Country (433 Mhz)	10	71	Continental	28155	7004	7000K	1043	7000K	68078768AA
Chrysler	Town & Country (433 Mhz)	11	---	Schrader	20398			9398	VS950	56029398AB
Chrysler	Voyager(433 Mhz)	02-03	35	Schrader	20028	7004	7000K	9028	1080K	52088990AC
**The 1050K is to be used on the Siemens sensors and the 2030K is to be used on the Schrader sensors.										
Dodge	Avenger	08-10	71	Siemens	20066	7001	7000K	1051	1050	68001696AB
Dodge	Avenger	10-11	71	Continental		7001	7000K	1051	7000K	68078861AA
Dodge	Caliber	07-10	71	Siemens	20066	7001	7000K	1051	1050K	68001696AB
Dodge	Caliber	10-11	71	Continental		7001	7000K	1051	7000K	68078861AA
Dodge	Caravan(433 Mhz)	02-03	35	Schrader	20028	7004	7000K	9028	1080K	52088990AC
Dodge	Caravan	04-05	71	Siemens	20335	7001	7000K	1052	1050K	04727392AB
Dodge	Caravan	06-07	71	Siemens	20066	7001	7000K	1051	1050K	56053030AB
Dodge	Challenger (433 Mhz)	08	71	Continental	28155	7004	7000K	1043	1050K	68001698AB
Dodge	Challenger--SRT (433 Mhz)	09-11	71	Schrader	28214/28291			9214	2030K	56029400AD
Dodge	Challenger	10-11	---	Schrader	20398			9398	VS950	56029398AB
Dodge	Charger	06-07	71	Siemens	20066	7001	7000K	1051	1050K	68001696AB
Dodge	Charger(433 Mhz)	08	71	Continental	28155	7004	7000K	1043	1050K	68001698AB
Dodge	Charger(433 Mhz)-SRT	09-10	71	Schrader	28214/28291			9214	2030K	56029400AC
Dodge	Charger(Alloy)	10-11	---	Schrader	20398			9398	VS950	56029398AB
Dodge	Dakota	08-10	53	Schrader	28154	7001	7000K	9154	2030K	56029319AC
Dodge	Dakota	11	---	Schrader	20308	7001	7000K	9308	VS950	56029479AA
Dodge	Dakota	11	71	Schrader	---	7001	7000K	1051	1050K	Sensor Replacement Only

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	OE Supplier	Schrader Sensor #	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	OE Sensor Part #
Dodge	Durango	07-09	71	Schrader	20066	7001	7000K	1051 **	1050K or 2030K	56029465AB
Dodge	Durango	11	---	Schrader				9398	VS950	56029398AB
Dodge	Grand Caravan(433 Mhz)	02-03	35	Schrader	20028	7004	7000K	9028	1080K	52088990AC
Dodge	Grand Caravan	04-05	71	Siemens	20335	7001	7000K	1052	1050K	04727392AB
Dodge	Grand Caravan	06-07	71	Siemens	20066	7001	7000K	1051	1050K	56053030AB
Dodge	Grand Caravan (433 Mhz)	08-10	71	Continental	28155	7004	7000K	1043	1050K	68001698AB
Dodge	Grand Caravan (433 Mhz)	10-11	71	Continental		7004	7000K	1043	7000K	68078768AA
Dodge	Intrepid(433 Mhz)	02-04	35	Schrader	20028	7004	7000K	9028	1080K	52088990AC
Dodge	Journey(433 Mhz)	09-10	71	Continental	28155	7004	7000K	1043	1050K	68001698AB
Dodge	Journey(433 Mhz)	10-11	71	Continental		7004	7000K	1043	7000K	68078768AA
Dodge	Magnum	05-07	71	Siemens	20066	7001	7000K	1051	1050K	68001696AB
Dodge	Magnum(433 Mhz)	08	71	Continental	28155	7004	7000K	1043	1050K	68001698AB
Dodge	Magnum(433 Mhz)	09	71	Schrader	28214			9214	2030K	56029400AD
Dodge	Nitro	07-11	71	Schrader	20066	7001	7000K	1051 **	1050K or 2030K	56029465AB
Dodge	Nitro(Alloy)	10-11	---	Schrader	28308	7001	7000K	9308	VS950	56029479AA
Dodge	Nitro(Alloy)	10-11	---	Schrader	---	7001	7000K	1051	1050K	Sensor Replacement Only
Dodge	Ram(HP-315 Mhz) 1500/2500	08-09	53	Schrader	28154			9154	2030K	56029319AC (Check VIN)
Dodge	Ram(433 Mhz) 1500	09	71	Continental	28155	7004	7000K	1043	1050K	56029359AC
Dodge	Ram(433 Mhz) 1500/2500	10-11	---	Schrader	20398			9398	VS950	56029398AB
Dodge	Sprinter	07-10	54	Siemens	20089			1042	1098K	68038945AA
Dodge	Stratus	07	71	Siemens	20066	7001	7000K	1051	1050K	56053030AB
Dodge	Viper(433 Mhz)	03-10	35	Schrader	20028	7004	7000K	9028	1080K	52088990AC
**The 1050K is to be used on the Siemens sensors and the 2030K is to be used on the Schrader sensors.										
Ferrari	430(433 Mhz)	06-07	---	Beru	20077			9001	1090K	22 45 49
Ferrari	430(433 Mhz)	08-11	---	Beru				9007	1090K	23 92 98
Ferrari	458(433 Mhz)	10-11	---	Beru				9008	1090K	24 88 87
Ferrari	550(433 Mhz)	02-10	---	Beru	20077			9001	1090K	22 45 49
Ferrari	575(433 Mhz)	02-06	---	Beru	20077			9001	1090K	22 45 49
Ferrari	575(315 Mhz)	02-05	---	Beru				9004	1090K	22 45 48
Ferrari	599	04-10	---	Beru				9001	1090K	22 45 49
Ferrari	612(433 Mhz)	02-10	---	Beru	20077			9001	1090K	22 45 49
Ferrari	California(433 Mhz)	10	---	Beru				9008	1090K	24 88 87
Ferrari	Enzo(433 Mhz)	03-09	---	Beru	20084			9005	1090K	22 45 51
Ferrari	FXX(433 Mhz)	03-09	---	Beru	20084			9005	1090K	22 45 51
Ferrari	Spider(433 Mhz)	02-09	---	Beru	20077			9001	1090K	22 45 49
Ford	Crown Victoria	06-11	---	Lear	28385/28390	7001	7000K	1048	NA	6F2Z-1A189A
Ford	E Series	07-09	---	Lear	28395			1048-HP	NA	8C2Z-1A189A
Ford	E Series(HP)	10-11	---	Schrader	20315			9315	VS950	9L3Z-1A189-A
Ford	Edge	07-10	---	Lear	28385/28390	7001	7000K	1048	NA	7L1Z-1A189A
Ford	Edge	11	---	Schrader	20315	7001	7000K	9315	VS950	9L3Z-1A189-A
Ford	Escape	06-08	---	Lear	28385/28390	7001	7000K	1048	NA	6F2Z-1A189A
Ford	Escape	09-11	---	Schrader	20315	7001	7000K	9315	VS950	9L3Z-1A189-A
Ford	Expedition(433 Mhz)	03-04	44	Schrader	20096	7004	7000K	9096	1060K	4L2T1A150BA
Ford	Expedition(315 Mhz)	05-06	44	Schrader	20135	7001	7000K	9135	1060K	5L1ZA150AB
Ford	Expedition	07-10	---	Lear	28385/28390	7001	7000K	1048	NA	7L1Z-1A189A
Ford	Expedition	11	---	Schrader	20315	7001	7000K	9315	VS950	9L3Z-1A189-A
Ford	Explorer(433 Mhz)	03-05	44	Schrader	20096	7004	7000K	9096	1060K	4L2T1A150BA
Ford	Explorer	06-10	---	Lear	28385/28390	7001	7000K	1048	NA	6F2Z-1A189A
Ford	Explorer	11	---	Schrader	20315	7001	7000K	9315	VS950	9L3Z-1A189-A

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	OE Supplier	Schrader Sensor #	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	OE Sensor Part #
Ford	Explorer Sport Trac	07-10	---	Lear	28385/28390	7001	7000K	1048	NA	6F2Z-1A189A
Ford	F 150	07-08	---	Lear	28385/28390	7001	7000K	1048	NA	6F2Z-1A189A
Ford	F 150	09-11	---	Schrader	20315	7001	7000K	9315	VS950	9L3Z-1A189-A
Ford	Fiesta	11	---	Schrader	20315	7001	7000K	9315	VS950	9L3Z-1A189-A
Ford	500	08-09	---	Lear	28385/28390	7001	7000K	1048	NA	6F2Z-1A189A
Ford	Flex	09-10	---	Lear	28385/28390	7001	7000K	1048	NA	7L1Z-1A189A
Ford	Flex	11	---	Schrader	20315	7001	7000K	9315	VS950	9L3Z-1A189-A
Ford	Focus	07-09	---	Lear	28385/28390	7001	7000K	1048	NA	6F2Z-1A189A/ 7L1Z-1A189A
Ford	Focus	10-12	---	Schrader	20315	7001	7000K	9315	VS950	9L3Z-1A189-A
Ford	Freestar(315 Mhz)	04-05	44	Schrader	20135	7001	7000K	9135	1060K	5L1ZA150AB
Ford	Freestar	06-09	---	Lear	28385/28390	7001	7000K	1048	NA	6F2Z-1A189A
Ford	Fusion	07-09	---	Lear	28385/28390	7001	7000K	1048	NA	6F2Z-1A189A
Ford	Fusion	10-11	---	Schrader	20315	7001	7000K	9315	VS950	9L3Z-1A189-A
Ford	Mustang	07-09	---	Lear	28385/28390	7001	7000K	1048	NA	6F2Z-1A189A
Ford	Mustang	10-11	---	Schrader	20315	7001	7000K	9315	VS950	9L3Z-1A189-A
Ford	Ranger	07-11	---	Lear	28385/28390	7001	7000K	1048	NA	6F2Z-1A189A
Ford	Super Duty (250/350/450) Pre-June 2009	07-10	---	Lear	28395			1048HP	NA	8C2Z-1A189A
Ford	Super Duty (250/350/450) Post-June 2009	10-11	---	Schrader	20315			9315	VS950	9L3Z-1A189-A
Ford	Taurus(Pre-May 2010)	08-10	---	Lear	28385/28390	7001	7000K	1048	NA	7L1Z-1A189A
Ford	Taurus(Post-May 2010)	11	---	Schrader	20315	7001	7000K	9315	VS950	9L3Z-1A189-A
Ford	Taurus X	08-09	---	Lear	28385/28390	7001	7000K	1048	NA	7L1Z-1A189A
Ford	Transit	10-11	---	Schrader	20315	7001	7000K	9315	VS950	9L3Z-1A189-A
GMC	Acadia	07-08	80	Siemens	20158	7001	7000K	1047	1050K	15921013
GMC	Acadia	09-11	---	Schrader	20153	7001	7000K	9153	VS950	25920615
GMC	Canyon	07-11	62	Schrader	20131			9131	1110K	15122618
GMC	Envoy	05-07	62	Schrader	20116	7001	7000K	9116	1070K	25774006
GMC	Envoy	07-09	---	Schrader	20153	7001	7000K	9153	VS950	25920615
GMC	Savana	08-09	80	Siemens	20158	7001	7000K	1047	1050K	15921013
GMC	Savana	10-11	---	Schrader	20153	7001	7000K	9153	VS950	25920615
GMC	Sierra(all)	04	62	Schrader	20115			9115	1070K	15136883
GMC	Sierra(all)	05-06	62	Schrader	20107			9107	1070K	15114379
GMC	Sierra(all)	07	62	TRW		7001	7000K	NA	2020K	15825475
GMC	Sierra(all)	07	80	Siemens	20158	7001	7000K	1047	1050K	TRW Sensor Replacement
GMC	Sierra(all)	07-11	---	Schrader	20153	7001	7000K	9153	VS950	25920615
GMC	Terrain	10-11	---	Schrader	20153/28206	7001	7000K	9153	VS950	12768826
GMC	Yukon(all)	04	62	Schrader	20115			9115	1070K	15136883
GMC	Yukon(all)	05-06	62	Schrader	20107			9107	1070K	15114379
GMC	Yukon(all)	07	62	TRW		7001	7000K	NA	2020K	15825475
GMC	Yukon(all)	07	80	Siemens	20158	7001	7000K	1047	1050K	TRW Sensor Replacement
GMC	Yukon(all)	07-11	---	Schrader	20153	7001	7000K	9153	VS950	25920615
Honda	Accord	08-11	35	Pacific	20099			1208	1100K	42753-SWA-315/316
Honda	Civic	08-11	35	TRW	28720			1212	2040K	42753-SNA-A83
Honda	CR-V(Both)	07-11	35	Pacific	20099			1208	1100K	42753-SWA-315/316
Honda	CR-Z	11	35	TRW	28720			1212	2040K	42753-SNA-A83
Honda	Crosstour	10-11		Continental	20100		7000K	5511	7000K	42753-TP6-A82
Honda	Element	06-07	35	TRW	28983			1058	2000K	06421-SCV-A01
Honda	Element	08	35	TRW	28983			1058	2040K or 2000K	42753-SHJ-A82
Honda	Element	09-11	35	TRW	28720			1212	2040K	42753-SNA-A83
Honda	Fit	08	35	Pacific	20099			1208	1100K	42753-SWA-315/316
Honda	Fit	09-11	35	TRW	28720			1212	2040K	42753-SNA-A83
Honda	Insight	10-11	35	TRW	28720			1212	2040K	42753-SNA-A83
Honda	Odyssey EX, EX-L, LX	06-07	35	TRW	28983			1058	2000K	06421-SCV-A00
Honda	Odyssey EX, EX-L, LX	08-10	35	TRW	28983			1058	2040K or 2000K	42753-SHJ-A82

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	OE Supplier	Schrader Sensor #	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	OE Sensor Part #
Honda	Odyssey EX, EX-L, LX	11	35	TRW	28720			1212	2040K	42753-SNA-A83
Honda	Odyssey Touring	05-07	35	TRW	28981			1057	2000K	06421-S3V-A04
Honda	Odyssey Touring	08-10	35	TRW	28981			1057	2040K or 2000K	42753-SHJ-A53
Honda	Odyssey Touring	11	35	TRW	28720			1212	2040K	42753-SNA-A83
Honda	Pilot(Steel)-2.25"	05	35	TRW	28982			1059	2000K	06421-S9V-A02
Honda	Pilot-1.75"	05-08	35	TRW	28981			1057	2000K	06421-S3V-A04
Honda	Pilot	09-11	35	Pacific	20098			1209	1100K	42753-STK-A04
Honda	Pilot(Steel)	09-10		Pacific						42753-SZA-A12
Honda	Ridgeline(RT)-2.25"	06-08	35	TRW	28982			1059	2000K	06421-S9V-A02
Honda	Ridgeline-1.75"	06-11	35	TRW	28981			1057	2000K	06421-S3V-A04
Honda	Ridgeline(Alloy)	09-11	35	TRW	28981			1057	2040K or 2000K	42753-SHJ-A53
Honda	S2000	08-09	35	Pacific				NA	1100K	42753-S2A-315
Hummer	H2	08-10	---	Schrader	20153	7001	7000K	9153	VS950	25920615
Hummer	H3	06-10	62	Schrader	20131			9131	1110K	15122618
Hummer	H3T	09-10	62	Schrader	20131			9131	1110K	15122618
Hyundai	Accent(Lo-Line)	08-11	31-40	TRW	28849	1206-A	1100K	1029**	2040K	52933-2F000
Hyundai	Azera	07-11	31-40	Beru	20086			1068	2000K	52933-2G200
Hyundai	Elantra	07-11	31-40	Beru	20086			1068	2000K	52933-2G200
Hyundai	Elantra(Touring)	10-11	71	Continental		7001	7020K	5507	1050K or 7020K	52933-2L500 or 52933-2M000
Hyundai	Entourage	07-10	31-40	Beru	20085			1028	2000K	52933-4D200
Hyundai	Equus	11	31-40	TRW	28849	1206-A	1100K	1029	2040K	52933-2F000
Hyundai	Genesis(Hi-line)	09-11	31-40	TRW	28849	1206-A	1100K	1029	2040K	52933-2F000
Hyundai	Genesis Coupe	10-11	71	Continental	20092	7001	7020K	5507	7020K	52933-2M000
Hyundai	Santa Fe (Thru July 2007)	07-08	31-40	Beru	20085			1028	2000K	52933-4D200
Hyundai	Santa Fe (Thru Sept 2009)	08-10	31-40	Beru	20086			1068	2000K	52933-2G200
Hyundai	Santa Fe(Oct 2009)	10-11	11	Lear				NEW	VS1010	52933-0W100
Hyundai	Santa Fe(Oct 2009)	10-11	31-40					1068	2000K	Sensor Replacement Only
Hyundai	Sonata	07-08	31-40	TRW	28983			1058	2000K	52933-3E000
Hyundai	Sonata(Lo-Line) --Late '08 Builds	08-10	31-40	TRW	28849	1206-A	1100K	1029**	2040K	52933-2F000
Hyundai	Sonata	11	71	Continental		7001	7020K	5507	7020K	52933-2M000
Hyundai	Tiburon	07-08	31-40	TRW	28983			1058	2000K	52933-3E000
Hyundai	Tucson	07-10	31-40	TRW	28983			1058	2000K	52933-3E000
Hyundai	Tucson	10-11	31-40	TRW	28849	1206-A	1100K	1029	2040K	52933-2F000
Hyundai	Veracruz	06-08	31-40	Beru	20085			1028	2000K	52933-4D200
Hyundai	Veracruz	08-11	31-40	Beru	20086			1068	2000K	52933-2G200
**	Note: Use "TRW LoLine Fxd Dly" function on BarTec 400 or 400P to program the sensors.									
Infiniti	EX35	08	45-60	Schrader	20064			9064	1080K	40700-CD001
Infiniti	EX35	09-10	66	Pacific	28210	**7001	7000K	9204	2030K	40700-JK00C
Infiniti	EX35	11		Pacific				1216	1100K	40700-1LA0C
Infiniti	FX35	03-08	45-60	Schrader	20064			9064	1080K	40700-CD001
Infiniti	FX35	08-10	66	Pacific	28204/28210	**7001	7000K	9204	2030K	40700-JK00C
Infiniti	FX35	11		Pacific				1216	1100K	40700-1LA0C
Infiniti	FX45	03-08	45-60	Schrader	20064			9064	1080K	40700-CD001
Infiniti	FX50	09-10	66	Pacific	28210	**7001	7000K	9204	2030K	40700-JK00C
Infiniti	FX50	11		Pacific				1216	1100K	40700-1LA0C
Infiniti	G25	11		Pacific				1216	1100K	40700-1LA0C
Infiniti	G35	03-06	45-60	Schrader	20064			9064	1080K	40700-CD001
Infiniti	G35	07-08	66	Pacific	28204/28210	**7001	7000K	9204	2030K	40700-JK00C
Infiniti	G37	08-10	66	Pacific	28210	**7001	7000K	9204	2030K	40700-JK00C
Infiniti	G37	11		Pacific				1216	1100K	40700-1LA0C
Infiniti	M35	06-07	45-60	Schrader	20064			9064	1080K	40700-CD001
Infiniti	M35	08-10	66	Schrader	28204	**7001	7000K	9204	2030K	40700-1AA0C

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	OE Supplier	Schrader Sensor #	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	OE Sensor Part #
Infiniti	M37	11		Pacific				1216	1100K	40700-1LA0C
Infiniti	M45	03-07	45-60	Schrader	20064			9064	1080K	40700-CD001
Infiniti	M45	08-10	66	Schrader	28204	**7001	7000K	9204	2030K	40700-1AA0C
Infiniti	M56	11		Pacific				1216	1100K	40700-1LA0C
Infiniti	Q45(pre-July)	03-06	45-60	Schrader	20064			9064	1080K	40700-CD001
Infiniti	Q45(Post-Aug)	06	66	Schrader	28204	**7001	7000K	9204	2030K	40700-JA01B
Infiniti	QX4	03	45-60	Schrader	20064			9064	1080K	40700-CD001
Infiniti	QX56(Steel)	05-06	49	Schrader	20069			9069	1130K	40700-CK002
Infiniti	QX56(Alloy)	04-07	49	Schrader	20161			9161	1080K	40700-CK001
Infiniti	QX56(Post-April)	07-10	66	Pacific	28204	**7001	7000K	9204	2030K	40700-JK00C
Infiniti	Q56	11		Pacific				1216	1100K	40700-1LA0C
**Must utilize the ATEQ VT-55 for the vehicle relearn.										
Isuzu	Ascender	06-08	62	Schrader	20116	7001	7000K	9116	1070K	25774006
Isuzu	I-290	07-08	62	Schrader	20131			9131	1110K	15122618
Isuzu	I-370	07-08	62	Schrader	20131			9131	1110K	15122618
Isuzu	Rodeo(433 Mhz)	04	35	Schrader	20028	7004	7000K	9028	1080K	52088990AC
Jaguar	S(315 Mhz)	05-09	71	Siemens	20090		7020K	1055	1050K	C2Z15017
Jaguar	S(433 Mhz)	05-09	71	Siemens	20091		7020K	1046	1050K	C2Z15016
Jaguar	XF(315 Mhz)	09-10	71	Siemens	20090		7020K	1055	1050K	C2Z15017
Jaguar	XF(315 Mhz)	10-11	71	Continental			7020K	1055	7020K	C2Z15017
Jaguar	XF(433 Mhz)	09-10	71	Siemens	20091		7020K	1046	1050K	C2Z15016
Jaguar	XF(433 Mhz)	10-11	71	Continental			7020K	1046	7020K	C2Z15016
Jaguar	XJ(315 Mhz)	04-10	71	Siemens	20090		7020K	1055	7020K	C2Z15017
Jaguar	XJ(315 Mhz)	10-11	71	Continental			7020K	1055	7020K	C2Z15017
Jaguar	XJ(433 Mhz)	04-10	71	Siemens	20091		7020K	1046	1050K	C2Z15016
Jaguar	XJ(433 Mhz)	10-11	71	Continental			7020K	1046	7020K	C2Z15016
Jaguar	XK(315 Mhz)	05-10	71	Siemens	20090		7020K	1055	7020K	C2Z15017
Jaguar	XK(315 Mhz)	10-11	71	Continental			7020K	1055	7020K	C2Z15017
Jaguar	XK(433 Mhz)	07-10	71	Siemens	20091		7020K	1046	1050K	C2Z15016
Jaguar	XK(433 Mhz)	10-11	71	Continental			7020K	1046	7020K	C2Z15016
Jeep	Commander	06-07	71	Siemens	20066	7001	7000K	1051	1050K	56029465AB
Jeep	Commander (433 Mhz)	08-10	71	Schrader	28155	7004	7000K	1043 **	1050K or 2030K	56029359AB
Jeep	Compass	07-10	71	Siemens	20066	7001	7000K	1051	1050K	68001696AB
Jeep	Compass	10-11	71	Continental		7001	7000K	1051	7000K	68078861AA
Jeep	Grand Cherokee(433 Mhz)	02-04	64	Schrader	20028	7004	7000K	9028	1080K	52088990AC
Jeep	Grand Cherokee	05-07	71	Siemens	20066	7001	7000K	1051	1050K	68001696AB
Jeep	Grand Cherokee (433 Mhz)	08-10	71	Schrader	28155	7004	7000K	1043 **	1050K or 2030K	56029359AB
Jeep	Grand Cherokee	11	---	Schrader	20398			9398	VS950	56029398AA
Jeep	Liberty(433 Mhz)	04	64	Schrader	20028	7004	7000K	9028	1080K	52088990AC
Jeep	Liberty	05-06	71	Siemens	20066	7001	7000K	1051	1050K	56029465AB
Jeep	Liberty	07-08	71	Schrader	20066	7001	7000K	1051 **	1050K or 2030K	56029465AB
Jeep	Liberty(433 Mhz)	09	71	Schrader	28155	7004	7000K	1043 **	1050K or 2030K	56029359AB
Jeep	Liberty	10-11	---	Schrader	28308	7001	7000K	9308	VS950	56029479AA
Jeep	Liberty	10	---	Schrader	20066	7001	7000K	1051	1050K	68001696AA

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	OE Supplier	Schrader Sensor #	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	OE Sensor Part #
Jeep	Patriot	07-10	71	Siemens	20066	7001	7000K	1051	1050K	68001696AB
Jeep	Patriot	10-11	71	Continental		7001	7000K	1051	7000K	68078861AA
Jeep	Wrangler(Alloy)	07-08	71	Schrader	20066	7001	7000K	1051 **	1050K or 2030K	56029465AB
Jeep	Wrangler(Alloy)	09-10	71	Schrader	28155	7004	7000K	1043 **	1050K or 2030K	56029359AB
Jeep	Wrangler	10-11	---	Schrader	28308	7001	7000K	9308	VS950	56029479AA
Jeep	**The 1050K is to be used on the Siemens sensors and the 2030K is to be used on the Schrader sensors.									
KIA	Amanti	07-09	31-40	TRW	28983			1058	2000K	52933-3E000
KIA	Borrego(Lo-Line)	09	31-40	TRW	28849	1206-A	1100K	1029**	2040K	52933-2F000
KIA	Forte	10-11	71	Continental	20092	7001	7020K	5507	7020K	52933-1M000
KIA	Magentis	08-10	31-40	Beru	20086			1068	2000K	52933-2G200
KIA	Mohave	09	31-40	TRW	28849	1206-A	1100K	1029**	2040K	52933-2F000
KIA	Optima(Hi-Line)	06-10	31-40	Beru	20086			1068	2000K	52933-2G200
KIA	Optima	11	71	Continental	20092	7001	7020K	5507	7020K	52933-2M000
KIA	Rio(Lo-Line)	08-11	31-40	TRW	28849	1206-A	1100K	1029**	2040K	52933-2F000
KIA	Rio 5(Lo-Line) -- Post 7/2/07	08-11	31-40	TRW	28849	1206-A	1100K	1029**	2040K	52933-2F000
KIA	Rondo(Hi-Line)	06-09	31-40	Beru	20086			1068	2000K	52933-2G200
KIA	Sedona(Lo-Line)	06-08	31-40	Beru	20085			1028	2000K	52933-4D200
KIA	Sedona(Hi-Line)	09-11	31-40	Beru	20086			1068	2000K	52933-2G200
KIA	Sorento	05-10	31-40	TRW	28983			1058	2000K	52933-3E000
KIA	Sorento	11	71	Continental	20092	7001	7020K	5507	7020K	52933-2M000
KIA	Soul	10-11	71	Continental	20092	7001	7020K	5507	7020K	52933-2M000
KIA	Spectra-5(Lo-Line)	07-09	31-40	TRW	28849	1206-A	1100K	1029**	2040K	52933-2F000
KIA	Sportage	06-08	31-40	TRW	28983			1058	2000K	52933-3E000
KIA	Sportage(Lo-Line)	09-11	31-40	TRW	28849	1206-A	1100K	1029**	2040K	52933-2F000
KIA	Tuscany	07-08	31-40	TRW	28983			1058	2000K	Enhanced/Basic
**	Note: Use "TRW LoLine Fxd Dly" function on BarTec 400 or 400P to program the sensors.									
Land Rover	LR2(315 Mhz)	08-09	71	Siemens			7020K	NEW	1050K	---
Land Rover	LR2(315 Mhz)	10-11	71	Continental	20090		7020K	1055	7020K	LR021936
Land Rover	LR3(433 Mhz)	02-05	58	Beru	28082			9003	1090K	YDB 0000 60
Land Rover	LR3(315 Mhz)	06-09	71	Siemens	20090		7020K	1055	1050K	LR018860
Land Rover	LR3(433 Mhz)	06-09	71	Siemens	20091		7020K	1046	1050K	LR018861
Land Rover	LR4(315 Mhz)	10-11	71	Continental	20090		7020K	1055	7020K	LR021936
Land Rover	Range Rover (315 Mhz)	06-09	71	Siemens	20090		7020K	1055	1050K	LR018860
Land Rover	Range Rover (315 Mhz)	10-11	71	Continental	20090		7020K	1055	7020K	LR021936
Land Rover	Range Rover (433 Mhz)	06-10	71	Siemens	20091		7020K	1046	1050K	LR018861
Land Rover	Range Rover Sport(315 Mhz)	06-09	71	Siemens	20090		7020K	1055	1050K	LR021936
Land Rover	Range Rover Sport(315 Mhz)	10-11	71	Continental	20090		7020K	1055	7020K	LR021936
Land Rover	Range Rover Sport(433 Mhz)	06-10	71	Siemens	20091		7020K	1046	1050K	LR018861

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	OE Supplier	Schrader Sensor #	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	OE Sensor Part #
Lexus	CT	11	35	Pacific	28370	1204-A	1100K	1204	1100K	42607-33021
Lexus	ES	07-11	35	Pacific	28370	1204-A	1100K	1204	1100K	42607-33021
Lexus	GS	05-11	35	Pacific	28335/28370	1204-A	1100K	1204	1100K	42607-33021
Lexus	GX470	04-06	35	Pacific	28345	1204-A	1100K	1205	1110K	42607-35010
Lexus	GX	06-11	35	Pacific	28365/28370	1204-A	1100K	1204	1100K	42607-33021
Lexus	HS Series	10	35	Pacific	20101	1204-A	1100K	1204	1100K	42607-75010
Lexus	IS Series	06-11	35	Pacific	28370	1204-A	1100K	1204	1100K	42607-33021
Lexus	LS	07-11	35	Pacific	28370	1204-A	1100K	1204	1100K	42607-33021
Lexus	LX	05-11	35	Pacific	28365/28370	1204-A	1100K	1204	1100K	42607-33021
Lexus	RX	06-11	35	Pacific	28370	1204-A	1100K	1204	1100K	42607-33021
Lexus	SC430	02-07	27	Pacific				NA	1120K	42607-24040
Lexus	SC	07-10	35	Pacific	28370	1204-A	1100K	1204	1100K	42607-33021
Lincoln	Aviator(433 Mhz)	03-05	44	Schrader	20096	7004	7000K	9096	1060K	4L2T1A150-BA
Lincoln	Mark LT	07-08	---	Lear	28385/28390	7001	7000K	1048	NA	6F2Z-1A189A
Lincoln	MKS	09-10	---	Lear	28385/28390	7001	7000K	1048	NA	7L1Z-1A189A
Lincoln	MKS	11	---	Schrader	20315	7001	7000K	9315	VS950	9L3Z-1A189-A
Lincoln	MKT	11	---	Schrader	20315	7001	7000K	9315	VS950	9L3Z-1A189-A
Lincoln	MKX	07-10	---	Lear	28385/28390	7001	7000K	1048	NA	7L1Z-1A189A
Lincoln	MKX	11	---	Schrader	20315	7001	7000K	9315	VS950	9L3Z-1A189-A
Lincoln	MKZ	07-09	---	Lear	28385/28390	7001	7000K	1048	NA	6F2Z-1A189A
Lincoln	MKZ	10-11	---	Schrader	20315	7001	7000K	9315	VS950	9L3Z-1A189-A
Lincoln	Navigator(433 Mhz)	03-04	44	Schrader	20096	7004	7000K	9096	1060K	4L2T1A150-BA
Lincoln	Navigator(315 Mhz)	05-06	44	Schrader	20135	7001	7000K	9135	1060K	5L1Z1A150-AB
Lincoln	Navigator	07-10	---	Lear	28385/28390	7001	7000K	1048	NA	7L1Z-1A189A
Lincoln	Navigator	11	---	Schrader	20315	7001	7000K	9315	VS950	9L3Z-1A189-A
Lincoln	Town Car	06-11	---	Lear	28385/28390	7001	7000K	1048	NA	6F2Z-1A189A
Maserati	Quattroporte-- Thru December	04-09	35	Beru				9001	1090K	22 45 49
Maserati	Quattroporte-- Post January	10-11	35	Beru				9008	1090K	24 88 87
Maserati	Coupe-- Thru June	09	35	Beru				9001	1090K	22 45 49
Maserati	Coupe-- Post July	09-11	35	Beru				9008	1090K	24 88 87
Mazda	B Series	07-09	---	Lear	28385/28390	7001	7000K	1048	NA	6F2Z-1A189A
Mazda	2	11	71	Continental	20093	7001	7000K	1056	7000K	BBM2-37-140B
Mazda	3	04	71	Siemens- Fixed Angle	20093	7001	7000K	1056	NA	FE01-37-140A/ GN3A-37-140B
Mazda	3	05-10	71	Siemens	20093	7001	7000K	1056	1050K	BBM2-37-140B
Mazda	3	10-11	71	Continental	20093	7001	7000K	1056	7000K	BBM2-37-140B
Mazda	5	06-10	71	Siemens	20093	7001	7000K	1056	1050K	BBM2-37-140B
Mazda	5	10-12	71	Continental	20093	7001	7000K	1056	7000K	BBM2-37-140B
Mazda	6	05-10	71	Siemens	20093	7001	7000K	1056	1050K	BBM2-37-140B
Mazda	6	10-11	71	Continental	20093	7001	7000K	1056	7000K	BBM2-37-140B
Mazda	CX-7	07-10	71	Siemens	20093	7001	7000K	1056	1050K	BBM2-37-140B
Mazda	CX-7	10-11	71	Continental	20093	7001	7000K	1056	7000K	BBM2-37-140B
Mazda	CX-9	07-10	71	Siemens	20093	7001	7000K	1056	1050K	BBM2-37-140B
Mazda	CX-9	10-11	71	Continental	20093	7001	7000K	1056	7000K	BBM2-37-140B
Mazda	MX-5 Miata	06-10	71	Siemens	20093	7001	7000K	1056	1050K	BBM2-37-140B
Mazda	MX-5 Miata	10-11	71	Continental	20093	7001	7000K	1056	7000K	BBM2-37-140B
Mazda	RX-8	04	71	Siemens- Fixed Angle	20093	7001	7000K	1056	NA	FE01-37-140A/ GN3A-37-140B

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	OE Supplier	Schrader Sensor #	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	OE Sensor Part #
Mazda	RX-8	05-10	71	Siemens	20093	7001	7000K	1056	1050K	BBM2-37-140B
Mazda	RX-8	10-11	71	Continental	20093	7001	7000K	1056	7000K	BBM2-37-140B
Mazda	Speed 3	10-11	71	Siemens	20093	7001	7000K	1056	7000K	BBM2-37-140B
Mazda	Speed 6	07-08	71	Siemens	20093	7001	7000K	1056	1050K	BBM2-37-140B
Mazda	Tribute	06-08	---	Lear	28385/28390	7001	7000K	1048	NA	6F2Z-1A189A
Mazda	Tribute	09-11	---	Schrader	20315	7001	7000K	9315	VS950	ZZDA-37-140
M-Benz	C Class(433 Mhz)	07-12	53	Schrader	28214			9214	2030K	003 540 0217
M-Benz	CL Class(315 Mhz)	00-06	35	Beru				9004	1090K	000 822 34 06
M-Benz	CL Class(433 Mhz)	00-06	35	Beru				9001	1090K	000 822 3306
M-Benz	CL Class(433 Mhz)	09-10	53	Schrader	28214			9214	2030K	003 540 0217
M-Benz	CL 63-65-550-600 (315 Mhz)	07-11	53	Siemens	20094			1054	1040K	002 540 7917
M-Benz	CL 63-65-550-600 (433 Mhz)	07-11	53	Siemens	20095			1049	1040K	002 540 8017
M-Benz	CLKClass(315 Mhz)	06-07	35	Beru				9004	1090K	000 822 34 06
M-Benz	CLK Class(433 Mhz)	08-09	53	Schrader	28214			9214	2030K	003 540 0217
M-Benz	CLS 55-63-500-550 (315 Mhz)	06-11	53	Siemens	20094			1054	1040K	002 540 7917
M-Benz	CLS 55-63-500-550 (433 Mhz)	06-09	53	Siemens	20095			1049	1040K	002 540 8017
M-Benz	CLS Class(433 Mhz)	08-10	53	Schrader	28214			9214	2030K	003 540 0217
M-Benz	CLS Class(433 Mhz)	11	53	Siemens	20095			1049	1040K	002 540 8017
M-Benz	E Class(315 Mhz)	00-05	35	Beru				9004	1090K	000 822 34 06
M-Benz	E Class(433 Mhz)	00-05	35	Beru				9001	1090K	000 822 33 06
M-Benz	E Class(315 Mhz)	06-10	53	Siemens	20094			1054	1040K	002 540 7917
M-Benz	E Class(433 Mhz)	06-10	53	Siemens	20095			1049	1040K	002 540 8017
M-Benz	E Class(433 Mhz)	10-11	53	Schrader	28214			9214	2030K	003 540 0217
M-Benz	G Class(433 Mhz)	07-10	53	Schrader	28214			9214	2030K	003 540 0217
M-Benz	GL Class(315 Mhz)	07-09	53	Siemens	20094			1054	1040K	002 540 7917
M-Benz	GL Class(433 Mhz)	07-09	53	Siemens	20095			1049	1040K	002 540 8017
M-Benz	GL(433 Mhz)	10-11	53	Schrader	28214			9214	2030K	003 540 0217
M-Benz	GLK(433 Mhz)	10-11	53	Schrader	28214			9214	2030K	003 540 0217
M-Benz	ML Class(315 Mhz)	06-10	53	Siemens	20094			1054	1040K	002 540 7917
M-Benz	ML Class(433 Mhz)	06-10	53	Siemens	20095			1049	1040K	002 540 8017
M-Benz	ML Class(433 Mhz)	10-11	53	Schrader	28214			9214	2030K	003 540 0217
M-Benz	R Class(315 Mhz)	06-09	53	Siemens	20094			1054	1040K	002 540 7917
M-Benz	R Class(433 Mhz)	06-09	53	Siemens	20095			1049	1040K	002 540 8017
M-Benz	R Class(433 Mhz)	10	35	Schrader	28214			9214	2030K	003 540 0217
M-Benz	R Class(433 Mhz)	11	53	Siemens	20095			1049	1040K	002 540 8017
M-Benz	S Class(315 Mhz)	00-06	35	Beru				9004	1090K	000 822 34 06
M-Benz	S Class(433 Mhz)	00-06	35	Beru				9001	1090K	000 822 33 06
M-Benz	S Class(315 Mhz)	07-11	53	Siemens	20094			1054	1040K	002 540 7917
M-Benz	S Class(433 Mhz)	07-10	53	Siemens	20095			1049	1040K	002 540 8017
M-Benz	S(433 Mhz)	10-11	53	Schrader	28214			9214	2030K	003 540 0217
M-Benz	SL Class(315 Mhz)	00-05	35	Beru				9004	1090K	000 822 34 06
M-Benz	SL Class(433 Mhz)	00-05	35	Beru				9001	1090K	000 822 33 06
M-Benz	SL Class(315 Mhz)	06-11	53	Siemens	20094			1054	1040K	002 540 7917
M-Benz	SL Class(433 Mhz)	06-09	53	Siemens	20095			1049	1040K	002 540 8017
M-Benz	SLK Class(433 Mhz)	08-11	53	Schrader	28214			9214	2030K	003 540 0217

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	OE Supplier	Schrader Sensor #	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	OE Sensor Part #
M-Benz	SLR Class(315 Mhz)	04-06	35	Beru				9004	1090K	000 822 34 06
M-Benz	SLR Class(433 Mhz)	00-06	35	Beru				9001	1090K	000 822 33 06
M-Benz	SLR Class(315 Mhz)	08-09	53	Siemens	20094			1054	1040K	002 540 7917
M-Benz	SLR Class(433 Mhz)	08-09	53	Siemens	20095			1049	1040K	002 540 8017
M-Benz	SLS(433 mhz)	11	53	Schrader	28214			9214	2030K	003 540 0217
Mercury	Grand Marquis	07-10	---	Lear	28385/28390	7001	7000K	1048	NA	6F2Z-1A189A
Mercury	Mariner	06-08	---	Lear	28385/28390	7001	7000K	1048	NA	6F2Z-1A189A
Mercury	Mariner	09-11	---	Schrader	20315	7001	7000K	9315	VS950	9L3Z-1A189-A
Mercury	Milan	08-09	---	Lear	28385/28390	7001	7000K	1048	NA	6F2Z-1A189A
Mercury	Milan	10-11	---	Schrader	20315	7001	7000K	9315	VS950	9L3Z-1A189-A
Mercury	Montego	06-07	---	Lear	28385/28390	7001	7000K	1048	NA	6F2Z-1A189A
Mercury	Monterey(315 Mhz)	04-05	44	Schrader	20135	7001	7000K	9135	1060K	5L1Z1A150-AB
Mercury	Monterey	06-07	---	Lear	28385/28390	7001	7000K	1048	NA	6F2Z-1A189A
Mercury	Mountaineer(433 Mhz)	02-05	44	Schrader	20096	7004	7000K	9096	1060K	4L2T1A150-BA
Mercury	Mountaineer	06-10	---	Lear	28385/28390	7001	7000K	1048	NA	6F2Z-1A189A
Mercury	Sable	08-09	---	Lear	28385/28390	7001	7000K	1048	NA	7L1Z-1A189A
Mini	All(433 Mhz)	07-10	35	Beru	20083			1027	1090K	36 23 6 781 847
Mini	All(433 Mhz) (September 2009)	10-11	35	Beru	28081			9012	1090K	36 10 6 790 054
Mitsubishi	Eclipse(Alloy)	06-10	45-53	Schrader	20034			9034	1080K	MN103081
Mitsubishi	Eclipse(Steel)	06-07	45-53	Schrader	20069/28129			9069	1130K	4250A030
Mitsubishi	Eclipse	11	71	Continental		7001	7000K	1051	7000K	425 0B 975
Mitsubishi	Endeavor(433 Mhz)	04-06	45-53	Schrader	20028	7004	7000K	9028	1080K	52088990AC
Mitsubishi	Endeavor(Sept +)	06-11	45-53	Schrader	20034			9034	1080K	425 0B 877
Mitsubishi	Galant(433 Mhz)	04-06	45-53	Schrader	20028	7004	7000K	9028	1080K	MN103033
Mitsubishi	Galant	07-11	45-53	Schrader	20034			9034	1080K	425 0B 877
Mitsubishi	Galant(Steel)	07-09	45-53	Schrader	20069/28129			9069	1130K	4250A030
Mitsubishi	Lancer	08-10	71	Continental	28096	7001	7000K	1051	1050K	425 0B 668/975
Mitsubishi	Lancer	10-11	71	Continental	28096	7001	7000K	1051	7000K	425 0B 668/975
Mitsubishi	Montero	03-05	45-53	Schrader	20034			9034	1080K	MN103081
Mitsubishi	Outlander	07-10	71	Siemens	28096	7001	7000K	1051	1050K	425 0B 668/975
Mitsubishi	Outlander	10-11	71	Continental	28096	7001	7000K	1051	7000K	425 0B 668/975
Mitsubishi	Raider(HP)	08-09	53	Schrader	28154			9154	2030K	56029319AB
Nissan	350Z	04-06	45-60	Schrader	20064			9064	1080K	40700-CD001
Nissan	350Z	07-09	50-70	Schrader	28204	**7001	7000K	9204	2030K	40700-1AA0C
Nissan	370Z(Base)	09-10	50-70	Pacific		**7001	7000K	9204	2030K	40700-JK00C
Nissan	370Z(Base)	11	50-70	Pacific				1216	1100K	40700-1LA0C
Nissan	Altima	06-11	50-70	Schrader	28204	**7001	7000K	9204	2030K	40700-JA01B
Nissan	Armada(Alloy)--SE	05-08	49	Schrader	20161			9161	1080K	40700-CK001
Nissan	Armada(Steel)	05-06	49	Schrader	20069			9069	1130K	40700-CK002
Nissan	Armada-LE	08-11	50-70	Schrader	28204	**7001	7000K	9204	2030K	40700-JA01B
Nissan	Cube	09-11	50-70	Schrader	28204	**7001	7000K	9204	2030K	40700-1AA0B
Nissan	Frontier	03-04	45-60	Schrader	20064			9064	1080K	40700-CD001
Nissan	Frontier(Alloy)	05-08	49	Schrader	20161			9161	1080K	40700-CK001
Nissan	Frontier(Steel)	05-07	49	Schrader	20069			9069	1130K	40700-CK002
Nissan	Frontier(Steel)	08-11	50-70	Schrader	28204	**7001	7000K	9204	2030K	40700-1AA0B
Nissan	GT-R	09-11	50-70	Schrader	28204	**7001	7000K	9204	2030K	40700-1AA0C
Nissan	Juke	11	50-70	Schrader	28204	**7001	7000K	9204	2030K	40700-1AA0B
Nissan	Leaf	11		Pacific				1216	1100K	40700-1LA0C
Nissan	Maxima(Alloy)	06-07	49	Schrader	20161			9161	1080K	40700-CK001
Nissan	Maxima(Post-April)	07-11	50-70	Schrader	28204	**7001	7000K	9204	2030K	40700-1AA0B

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	OE Supplier	Schrader Sensor #	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	OE Sensor Part #
Nissan	Murano	03-06	45-60	Schrader	20064			9064	1080K	40700-CD001
Nissan	Murano	07-11	50-70	Schrader	28204	**7001	7000K	9204	2030K	40700-1AA0B
Nissan	NV 1500/2500HD/3500HD	12		Schrader				NEW		40700-1PA0A
Nissan	Pathfinder	03-04	45-60	Schrader	20064			9064	1080K	40700-CD001
Nissan	Pathfinder(Steel)	04	49	Schrader	20069			9069	1130K	40700-CK002
Nissan	Pathfinder	05-06	49	Schrader	20161			9161	1080K	40700-CK001
Nissan	Pathfinder	07-11	50-70	Schrader	28204/28167	**7001	7000K	9204	2030K	40700-1AA0B
Nissan	Quest(Steel)	04-07	49	Schrader	20069			9069	1130K	40700-CK002
Nissan	Quest(Alloy)	05-06	78	Schrader	20161			9161	1080K	40700-CK001
Nissan	Quest	07-09	50-70	Schrader	28204	**7001	7000K	9204	2030K	40700-JA01B
Nissan	Quest	11		Pacific				1216	1100K	40700-1LA0C
Nissan	Rogue	08-11	50-70	Schrader	28204	**7001	7000K	9204	2030K	40700-1AA0B
Nissan	Sentra(Alloy)	07-08	75	Schrader	20161			9161	1080K	40700-CK001
Nissan	Sentra(Steel)	07-11	50-70	Schrader	28204	**7001	7000K	9204	2030K	40700-1AA0B
Nissan	Titan(Alloy)	05-07	49	Schrader	20161			9161	1080K	40700-CK001
Nissan	Titan(Steel)	04-05	49	Schrader	20069			9069	1130K	40700-CK002
Nissan	Titan(Steel) (Post April)	07-11	50-70	Schrader	28204	**7001	7000K	9204	2030K	40700-JA01B
Nissan	Versa	07-11	50-70	Schrader	28204	**7001	7000K	9204	2030K	40700-JA01B
Nissan	Versa(Alloy)	07-08	71	Schrader	20161			9161	1080K	40700-CK001
Nissan	Xterra	03-04	45-60	Schrader	20064			9064	1080K	40700-CD001
Nissan	Xterra	05-06	49	Schrader	20161			9161	1080K	40700-CK001
Nissan	Xterra(Steel)	06-07	49	Schrader	20069			9069	1130K	40700-CK002
Nissan	Xterra	07-11	50-70	Schrader	28204/28167	**7001	7000K	9204	2030K	40700-1AA0B
**Must utilize the ATEQ VT-55 for the vehicle relearn.										
Pontiac	G3	09-10	---	Schrader	20153	7001	7000K	9153	VS950	25920615
Pontiac	G5	08	80	Siemens	20158	7001	7000K	1047	1050K	15921013
Pontiac	G5	09-10	---	Schrader	20153	7001	7000K	9153	VS950	25920615
Pontiac	G6(Pre-10/15)	08	80	Siemens	20158	7001	7000K	1047	1050K	15921013
Pontiac	G6(Post-10/15)	08-10	---	Schrader	20153	7001	7000K	9153	VS950	25920615
Pontiac	G8	08-09	---	Schrader	20153	7001	7000K	9153	VS950	25920615
Pontiac	Grand Prix	07-08	80	Siemens	20158	7001	7000K	1047	1050K	15921013
Pontiac	Grand Prix	08	---	Schrader	20153	7001	7000K	9153	VS950	25920615
Pontiac	Montana	08	80	Schrader	20158	7001	7000K	1047 ** 1050K or 1070K		15268606
Pontiac	Solstice	08-10	80	Siemens	20158	7001	7000K	1047	1050K	15921013
Pontiac	Torrent	07-09	80	Siemens	20158	7001	7000K	1047	1050K	10394110
Pontiac	Vibe	08-10	35	Pacific	28360	1204-A	1100K	1204	1100K	88974915
Pontiac	Wave	08-09	---	Schrader	20153	7001	7000K	9153	VS950	25920615
**The 1050K is to be used on the Siemens sensors and the 1070K is to be used on the Schrader sensors.										
Porsche	911(433 Mhz)	06-08	31-40	Beru				9001	1090K	997 606 021 01
Porsche	911(433 Mhz)	09-10	31-40	Beru	28087			9008	1090K	997 606 021 20
Porsche	911(433 Mhz)	11	31-40	Beru				9011	1090K	958 361 661 00
Porsche	911(315 Mhz)	06-08	31-40	Beru				9004	1090K	
Porsche	Boxster(433 Mhz)	06-08	31-40	Beru				9001	1090K	997 606 021 01
Porsche	Boxster(433 Mhz)-- Post November 2008	09-11	31-40	Beru	28087			9008	1090K	997 606 021 20
Porsche	Boxster(315 Mhz)	06-08	31-40	Beru				9004	1090K	
Porsche	Carrera GT(433 Mhz)	02-06	31-40	Beru				9001	1090K	997 606 021 01
Porsche	Cayenne(433 Mhz)	02-06	31-40	Beru				9005	1090K	955 361 661 01
Porsche	Cayenne(315 Mhz)	09-10	31-40	Beru				9004	1090K	955 606 023 01
Porsche	Cayenne(433 Mhz)	07-09	31-40	Beru				9007	1090K	955 606 021 00
Porsche	Cayenne(433 Mhz)	10-11	31-40	Beru				9011	1090K	958 361 661 00
Porsche	Cayman(433 Mhz)	06-08	31-40	Beru				9001	1090K	997 606 021 01
Porsche	Cayman(433 Mhz)	09-10	31-40	Beru	28087			9008	1090K	997 606 021 20
Porsche	Cayman(433 Mhz)	11	31-40	Beru				9011	1090K	958 361 661 00
Porsche	GT3	07-09	31-40	Beru				9001	1090K	997 606 021 01
Porsche	GT3	10-11	31-40	Beru	28087			9008	1090K	997 606 021 20
Porsche	Panamera(315 Mhz)	10-11	31-40	Beru				9004	1090K	997 606 023 21
Porsche	Panamera(433 Mhz)	10-11	31-40	Beru	28087			9008	1090K	997 606 021 20

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	OE Supplier	Schrader Sensor #	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	OE Sensor Part #
Rolls Royce	Phantom(433 Mhz)	07-10	31-40	Beru				1027	1090K	NA
Rolls Royce	Cabrio(433 Mhz)	07-10	31-40	Beru				1027	1090K	NA
Saab	9-3(433 Mhz)	04-07	62	Schrader	28078			9078	2010K	13172567
Saab	9-3(433 Mhz)	08-11	62	Schrader	20159				2010K	13227143
Saab	9-5(433 Mhz)	04-07	62	Schrader	28078			9078	2010K	13172567
Saab	9-5(433 Mhz)	08-10	62	Schrader	20159				2010K	13227143
Saab	9-7X(315 Mhz)	05-09	62	Schrader	20116	7001	7000K	9116	1070K	25774006
Saturn	Astra(433 Mhz)	08-09	62	Schrader	28078			9078	2010K	13172567
Saturn	Astra	10	---	Schrader	20153/28206	7001	7000K	9153	VS950	12768826
Saturn	Aura(<10/14/07)	07-08	80	Siemens	20158	7001	7000K	1047	1050K	15921013
Saturn	Aura(>10/14/07)	08-10	---	Schrader	20153	7001	7000K	9153	VS950	25920615
Saturn	Lamda Crossover	07-08	80	Schrader	20158	7001	7000K	1047 **	1050K or 1070K	15268606
Saturn	Outlook	07-08	80	Siemens	20158	7001	7000K	1047	1050K	15921013
Saturn	Outlook	09-10	---	Schrader	20153	7001	7000K	9153	VS950	25920615
Saturn	Sky	08-09	80	Siemens	20158	7001	7000K	1047	1050K	15921013
Saturn	Vue	07-10	---	Schrader	20153	7001	7000K	9153	VS950	25920615
**The 1050K is to be used on the Siemens sensors and the 1070K is to be used on the Schrader sensors.										
Scion	TC	06-11	35	Pacific	28365	1204-A	1100K	1204	1100K	42607-33011
Scion	XB	08-11	35	Pacific	28365	1204-A	1100K	1204	1100K	42607-33011
Scion	XD	08-11	35	Pacific	28365	1204-A	1100K	1204	1100K	42607-33011
Smart	Fortwo(433 Mhz)	08	53	Siemens				1049	1040K	004 542 1518
Smart	Fortwo(433 Mhz)	08-11	53	Schrader	28214			9214	2030K	003 540 0217
Subaru	B9 Tribeca	06-07	66	Schrader	20081			9081	1080K	28103AG00A
Subaru	Forester	08-11	---	Schrader	28203			9203	VS950	28103AG01C
Subaru	Impreza	08-11	---	Schrader	28203			9203	VS950	28103AG01C
Subaru	Legacy	04-07	66	Schrader	20081			9081	1080K	28103AG00A
Subaru	Legacy	08-11	---	Schrader	28203			9203	VS950	28103AG01C
Subaru	Outback	04-07	66	Schrader	20081			9081	1080K	28103AG00A
Subaru	Outback	08-11	---	Schrader	28203			9203	VS950	28103AG01C
Subaru	Tribeca	08-11	---	Schrader	28203			9203	VS950	28103AG01C
Suzuki	Equator	09-11	68	Schrader	28204			9204	2030K	43211-82200
Suzuki	Forenza	07-08	---	Schrader	20153	7001	7000K	9153	VS950	43130-85Z03
Suzuki	Grand Vitara	07-11	80	Schrader	20087			9087	2010K	43130-54J21
Suzuki	Kizashi	10-11	62	Continental	20066	7001	7000K	1051	7000K	43130-57L00
Suzuki	Reno	07-08	---	Schrader	20153	7001	7000K	9153	VS950	43130-85Z00
Suzuki	SX4	07-11	80	Schrader	20087			9087	2010K	43130-54J21
Suzuki	Verona	05-06	80	Schrader	20082			9082	2010K	43130-86Z20
Suzuki	XL-7	05-06	80	Schrader	20087			9087	2010K	43130-54J21
Suzuki	XL-7	07-10	62	Siemens	20158	7001	7000K	1047	1050K	43130-78J10
Tesla	Roadster	10	40-50	Baolong				2112	2020K	6004985
Toyota	4 Runner	03-05	35	Pacific	28345	1204-A	1100K	1205	1110K	42607-35010
Toyota	4 Runner	06-11	35	Pacific	28365/28370	1204-A	1100K	1204	1100K	42607-33021
Toyota	Avalon	07-11	35	Pacific	28360	1204-A	1100K	1204	1100K	42607-06011/33011
Toyota	Camry	07-11	35	Pacific	28360/28365	1204-A	1100K	1204	1100K	42607-06011/33011
Toyota	Corolla	07-11	35	Pacific	28370	1204-A	1100K	1204	1100K	42607-06011/33011/33021
Toyota	FJ Cruiser	08-11	35	Pacific	28365	1204-A	1100K	1204	1100K	42607-33011
Toyota	Highlander	07-11	35	Pacific	28365	1204-A	1100K	1204	1100K	42607-06011
Toyota	Land Cruiser	05-11	35	Pacific	28365	1204-A	1100K	1204	1100K	42607-33011
Toyota	Matrix	07-10	35	Pacific	28360/28365	1204-A	1100K	1204	1100K	42607-06011/33011
Toyota	Prius	06-11	35	Pacific	28365	1204-A	1100K	1204	1100K	42607-06011
Toyota	RAV 4	06-11	35	Pacific	28365/28370	1204-A	1100K	1204	1100K	42607-06011
Toyota	Sequoia(20 Degrees)	04-07	35	Pacific	28305	1204-A	1100K	1204	1110K	42607-0C020
Toyota	Sequoia(40 Degrees)	04-07	35	Pacific	28300	1204-A	1100K	1203	1110K	42607-0C010
Toyota	Sequoia(20 Degrees)	08-11	35	TRW	28670	1206-A	1100K	1206	1110K	42607-0C050/08010
Toyota	Sequoia(40 Degrees)	08	35	TRW	NA	1206-A	1100K	1206	1110K	42607-0C060

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	OE Supplier	Schrader Sensor #	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	OE Sensor Part #
Toyota	Sienna(20 Degrees)	06-11	35	TRW	28670	1206-A	1100K	1206	1110K	42607-0C050/42607-08010
Toyota	Solara	06-08	35	Pacific	28360	1204-A	1100K	1204	1100K	42607-06011
Toyota	Tacoma(20 Degrees)	05-06	35	Pacific	28305/28355	1204-A	1100K	1204	1110K	42607-0C020/AD020
Toyota	Tacoma(40 Degrees)	05-09	35	Pacific	28300/28380	1204-A	1100K	1203	1110K	42607-0C010/AD010/04010
Toyota	Tacoma(20 Degrees)	07-11	35	Pacific	28360	1204-A	1100K	1204	1100K	42607-06011
Toyota	Tundra(20 Degrees)	05-06	35	Pacific	28305	1204-A	1100K	1204	1110K	42607-0C020
Toyota	Tundra(40 Degrees)	05-06	35	Pacific	28300	1204-A	1100K	1203	1110K	42607-0C010
Toyota	Tundra(20 Degrees)	06-11	35	TRW	28670	1206-A	1100K	1206	1110K	42607-0C050/08010
Toyota	Tundra(40 Degrees)	06-11	35	TRW	NA	1206-A	1100K	1206	1110K	42607-0C060
Toyota	Venza	09-11	35	Pacific	28360	1204-A	1100K	1204	1100K	42607-06011
Toyota	Yaris	07-11	35	Pacific	28365	1204-A	1100K	1204	1100K	42607-33011
Volkswagen	Beetle	08-11	71	Siemens	20088			1053	1030K	1K0907253D
Volkswagen	CC	09-11	71	Siemens	20088			1053	1030K	1K0907253D
Volkswagen	EOS	07-11	71	Siemens	20088			1053	1030K	1K0907253D
Volkswagen	GLI	08-09	71	Siemens	20088			1053	1030K	1K0907253D
Volkswagen	Golf	10-11	71	Siemens	20088			1053	1030K	1K0907253D
Volkswagen	GTI(Standard Hex)	06-11	71	Siemens	20088			1053	1030K	1K0907253D
Volkswagen	GTI(O-ring Hex)	06-07	71	Siemens				1041	1031K	1K0907253E
Volkswagen	Jetta(Standard Hex)	06-11	71	Siemens	20088			1053	1030K	1K0907253D
Volkswagen	Passat(Standard Hex)	06-10	71	Siemens	20088			1053	1030K	1K0907253D
Volkswagen	Passat(433 Mhz)	11	35	Beru				NEW	1090K	3AA 907 275
Volkswagen	Passat(O-ring Hex)	06-08	71	Siemens				1041	1031K	1K0907253E
Volkswagen	Phaeton(433 Mhz) (thru May 2007)	02-07	35	Beru	20077			9001	1090K	4D0 907 275C
Volkswagen	Phaeton(433 Mhz) (June 2007)	07-10	35	Beru	20078			9007	1090K	4F0 907 275B
Volkswagen	Phaeton(433 Mhz)	11	35	Beru				9011	1090K	4F0 907 275D
Volkswagen	Phaeton(315 Mhz)	03 -07	35	Beru				9004	1090K	4D0 907 275A
Volkswagen	R32	08-10	71	Siemens	20088			1053	1030K	1K0907253D
Volkswagen	Rabbit(Standard Hex)	06-10	71	Siemens	20088			1053	1030K	1K0907253D
Volkswagen	Rabbit(O-ring Hex)	06-07	71	Siemens				1041	1031K	1K0907253E
Volkswagen	Routan(433 Mhz)	09-10	71	Siemens		7004	7000K	1043	1050K	7B0907253A
Volkswagen	Routan(433 Mhz)	11	---	Siemens				9398	VS950	7B0907253B
Volkswagen	Tiguan	09-11	71	Siemens	20088			1053	1030K	1K0907253D
Volkswagen	Touareg(433 Mhz)	02-06	35	Beru				9005	1090K	7L0 907 275B
Volkswagen	Touareg 2(433 Mhz)	07-10	35	Beru	20078			9007	1090K	4F0 907 275B
Volkswagen	Touareg 2(433 Mhz)	11	35	Bere				9011	1090K	4F0 907 275D
Volvo	C30(433 Mhz)	07-10	71	Siemens	20097		7020K	1044	1050K	31302096
Volvo	C30(433 Mhz)	10-11	71	Continental	20097		7020K	1044	7020K	31302096
Volvo	C70(433 Mhz)	07-10	71	Siemens	20097		7020K	1044	1050K	31302096
Volvo	C70(433 Mhz)	10-11	71	Continental	20097		7020K	1044	7020K	31302096
Volvo	S40(433 Mhz)	07-10	71	Siemens	20097		7020K	1044	1050K	31302096
Volvo	S40(433 Mhz)	10-11	71	Continental	20097		7020K	1044	7020K	31302096
Volvo	S60(315 Mhz)	04-10	44	Schrader	20156			9156	2010K	31200923
Volvo	S60(433 Mhz)	11	71	Siemens	20097		7020K	1044	7020K	31302096
Volvo	S80(315 Mhz)	04-07	44	Schrader	20156			9156	2010K	307489910
Volvo	S80(433 Mhz)	07-10	71	Siemens	20097		7020K	1044	1050K	31302096
Volvo	S80(433 Mhz)	10-11	71	Continental	20097		7020K	1044	7020K	31302096
Volvo	V50(433 Mhz)	08-10	71	Siemens	20097		7020K	1044	1050K	31302096
Volvo	V50(433 Mhz)	10-11	71	Continental	20097		7020K	1044	7020K	31302096
Volvo	V70(315 Mhz)	04-07	44	Schrader	20156			9156	2010K	307489910
Volvo	V70(433 Mhz)	08-10	71	Siemens	20097		7020K	1044	1050K	31302096

DILL TPMS APPLICATIONS CHART ©

OE	Model	Model Year	Torque In-Lbs	OE Supplier	Schrader Sensor #	Univ. Sensor	Univ. Kit	Dill Sensor #	Dill Kit #	OE Sensor Part #
Volvo	XC60	09-10	44	Schrader	20156			9156	2010K	31200923
Volvo	XC60	11		NEW						31201481
Volvo	XC70(315 Mhz)	04-07	44	Schrader	20156			9156	2010K	307489910
Volvo	XC70(433 Mhz)	08-10	71	Siemens	20097		7020K	1044	1050K	31302096
Volvo	XC70(433 Mhz)	10-11	71	Continental	20097		7020K	1044	7020K	31302096
Volvo	XC90(315 Mhz)	05-07	44	Schrader	20156			9156	2010K	31200923
Volvo	XC90(433 Mhz)	08	71		20097		7020K	1044	1050K	31302096
Volvo	XC90(315 Mhz)	09-11	44	Schrader	20156			9156	2010K	31200923

DISCLAIMER: The data presented in this document is accurate to the best of our knowledge and is regularly updated with the latest data available in the marketplace. We encourage you to check back for the latest edition of this data, however, we cannot guarantee accuracy of the information provided. Also, please note that several vehicle applications require knowledge of the VIN number as the sensor design could have changed mid-model year.

PLEASE DO NOT POST THIS DOCUMENT ON ANY WEBSITE.